REFURB SG371-SG606

SECTION 17

Interior U/S GRP Access Panels

1. Replace foam strips from around upper saloon access hatches shown in drawing below where necessary and adjust locks so that access hatches don't rattle when bus is in motion.

