

Asbestos Register

Client: LCETB.	Site Location: Scoil Mhuire ,Buncranna,Co.Donegal	Survey Date: 24/4/2019.
--------------------------	---	-----------------------------------

Area Surveyed	Location and Use of Material	Quantity (Approx)	Asbestos Type	Condition	Material Assessment.	Recommended Action.	Priority Assessment.	Next Assessment
Refurbishment/ demolition survey of the proposed work areas.								
Main Building	Slates to external walls	Not quantified	Chrysotile	Intact	3	Remove under controlled conditions prior to works that will disturb the materials.Manage in the interim.	1	
Home Economics Room	Heat pads to sinks	6 number	Chrysotile	Intact	4			

Asbestos Register

Estimated Costs	Reference Samples	Analysis.	Sample Reference
	Mastic sample Floor tile sample Slate sample Ceiling sample Heat pad sample Flat roof sample Pipework insulation sample Floor covering sample Pitched roof sample	NAD NAD Chrysotile NAD Chrysotile NAD NAD NAD NAD	MDK240419/01 MDK240419/02 MDK240419/03 MDK240419/04 MDK240419/05 MDK240419/06 MDK240419/07 MDK240419/08 MDK240419/09

0103

Glossary		*Asbestos fibre type	Commonly known as	*Quantity	Visual assessment of sample fibre content
NAD	No asbestos detected	Chrysotile	White asbestos	Trace	less than 2%
MMMF	Man made mineral fibre	Amosite	Brown asbestos	Significant	2% - 50%
		Crocidolite	Blue asbestos	Substantial	more than 50%

We wish to state that the analysis of the material(s) is limited to the sample(s) tested or examined. This does not guarantee that the balance of the material(s) from which the sample was taken is of equal proportion or contains the same constituents as those in the sample(s) tested. Analytical technique: Stereo and polarised light microscopy together with dispersion staining techniques based on The Analyst Guide HSG 248.