



## Fax Cover Sheet

**To: Aine**

**From: Evelyn Galvin  
Office of Public Works  
Health & Safety Unit  
51 St Stephens Green  
Dublin 2**

**Telephone: (00-353-1) 6476185  
Fax: (00-353-1) 6613104**

**NO OF PAGES: 6 (INCLUDING COVER SHEET)**

**MESSAGE:**

**Asbestos register as requested.**

**Regards,**

**Evelyn Galvin,  
Health & Safety Unit,  
1<sup>st</sup> July 2010.**

# SCHOOL'S PROGRAMME

## School's Details

|         |                                                 |
|---------|-------------------------------------------------|
| RN      | 72420E                                          |
| School  | Central Technical Institute / Vocational School |
| Address | Clonmel                                         |
| County  | TIPPERARY                                       |

Date surveyed: 09/06/1999 Survey type: 2

## File Details

|          |              |
|----------|--------------|
| File     | A365/4/28    |
| Prepared | 13/09/1999   |
| Location |              |
| Status   | FILE IN UNIT |

|                     |                                                                     |
|---------------------|---------------------------------------------------------------------|
| Asbestos identified | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
|---------------------|---------------------------------------------------------------------|

| Area Surveyed | Location                          | use of material | Asbestos Type          | Condition | Material A | Recommended Action        | Priority |
|---------------|-----------------------------------|-----------------|------------------------|-----------|------------|---------------------------|----------|
| Boiler Room   | 8x4 asbestos sheet stored in hall |                 |                        | Good      |            | Removed                   |          |
| Boiler Room   | Thermal insulation on pipework    |                 | Amosite and chrysotile | Very poor |            | Removed                   |          |
| Yard          | Vent pipe and cowl                |                 | Chrysotile             | Good      |            | Note in asbestos register |          |
| Floors        | Tiles                             |                 | None detected          |           |            |                           |          |

Latest survey link

# SCHOOL'S PROGRAMME

## School's Details

RN: 72420E

School: Vocational School

Address: Clonmel

County: TIPPERARY

File

Opened:

Location

Status:

File Details

A365/4/28

13/09/1999

P.A.

Asbestos Identifier

☒ Yes

☐ No

Date surveyed:

09/06/1999

Latest survey:

Survey type:

2

Survey

| Area Surveyed | Location                       | use of material | Asbestos Type   | Condition | Material Assessment       |
|---------------|--------------------------------|-----------------|-----------------|-----------|---------------------------|
| Boiler room   | Thermal insulation on pipework |                 | Amosite & chrys | Very poor | Removed                   |
| Yard          | Vent pipe and cowl             |                 | Chrysotile      | Good      | Note in asbestos register |
| Floors        | Tiles                          |                 | None detected   |           |                           |
| Boiler room   | Asbestos sheet stored in hall  |                 | Unknown         | Good      | Removed                   |

Survey Id details

| date removed | contractor | consultant | notes |
|--------------|------------|------------|-------|
| 01/11/1999   |            |            |       |

**Comments:**

June 1999.

Works carried out by DJV during November 1999 included: the removal and complete decontamination of amosite thermal insulation and residue from the boiler house of the school and the re-insulation with fibreglass preformed sections and 22g aluminium finish.

## ASBESTOS SURVEY.

|                                            |                                                               |                     |
|--------------------------------------------|---------------------------------------------------------------|---------------------|
| <b>Client:</b> OPW<br>Health & Safety Unit | <b>Site Details:</b> Clonmel VC<br>Co. Tipperary<br>RN 72420E | <b>Date:</b> 9/6/99 |
|--------------------------------------------|---------------------------------------------------------------|---------------------|

| Area Surveyed                    | Location and Use of Material      | Asbestos Type         | Condition | Recommended Action - Priority |
|----------------------------------|-----------------------------------|-----------------------|-----------|-------------------------------|
| All accessible and visible areas |                                   |                       |           |                               |
| Boiler Room                      | Thermal Insulation on pipework    | Amosite & Chrysotile. | Very Poor | Removed                       |
| Boiler entrance                  | 8x4 asbestos sheet stored in hall |                       | Good      | Removed                       |
| Yard                             | Vent pipe and cowl                | Chrysotile            | Good      | Note in Asbestos Register     |
| Floors.                          | Tiles.                            | None Detected.        |           |                               |

**General Comments:** Urgent action required to remove insulation from boiler house. Boiler house becomes completely flooded from river. Asbestos residues have contaminated all areas of boiler house.

| Estimated Removal Costs                                                                           | Location of Samples Taken                     | No. of Samples Taken |
|---------------------------------------------------------------------------------------------------|-----------------------------------------------|----------------------|
| £6000 Removal and Decontamination.<br>£2000 Replacement.<br>£2000 Air Monitoring and Supervision. | Boiler House<br>Boiler Ceiling.<br>Floor tile | 6.<br>CAL W6959.     |