

Magheroarty Pier Layout



Green line – Out Pan and Inpan to be surveyed

233M Total

0.6m piles approximately 388 Piles for inspection

Red Line – Out pans only

211M total

0.6M pile only every second pile available for inspections

176 Piles Approximately

Photos

Magheroarty Pier – Back face



Magheroarty Pier Inner Face



Magheroarty Pier head Inner face



Magheroarty Pier inner face

