Fence Inspection Report

Date: 10/12/2025

Location: Old Kenmare Road (51.980606, -9.532709)

Size of Fence:

- Perimeter: ~ 400 m
- Area: ~ 0.9 Ha

Summary of Issues:

- Broken Posts: At least 4. There may be posts that are rotten at the base and need replacement
- Complete fall down (deer access points)
    - approximately 7 m – mesh will need replaced
    - One large corner post has fallen down partially taking the mesh down with it;
- The two sheets of mesh that surround the fence line need to be secured to each other as there are gaps between them that sika deer can potentially enter though
- Fence (fence posts and mesh) are leaning is at least 4 places





Broken posts


10/12/2025 10:43



Fall downs



There are 4 places where the fence is leaning due to posts being unstable. Posts will need to re-stood and stabilised



The two sheets of mesh are not secured to each other leaving a large gap. The gap between the two needs to be closed along parts of the fence line.



There are parts of the fence where the mesh is sticking out or “messy”. Whilst not impacting the integrity of the fence the mesh needs to be tidied up. Note the post is also rotten at the bottom