



View of Building Block to be worked on



View of building to the rear with temporary flat roof edge protection visible.



View of existing roof. Single Ply PVC



View of ponding & temporary flat roof edge protection



View of present roof lining



View of faulty flashing detail




View of underside of roof hard deck from inside



View of water tank to be removed with stubs clearly visible. Stubs and tank to be removed along with pipe work from tank.



To be removed in total



Insulation Close up of roof build up Asphalt Bitumen Single Ply Trocal
(to remain)



Second view of tank to be removed



View of roof to be relined



Pipe work to be taken down and disposed of