

APPENDIX C

ASBESTOS DATA SHEETS



Scoil Ailbhe, Parnell Street, Thurles, Co. Tipperary

PHOENIX ENVIRONMENTAL SAFETY LTD. ASBESTOS DATA SHEET



Created By	Andrew Hickey
Date	22 nd February 2021
Site Details	Scoil Ailbhe, Parnell Street, Thurles, Co. Tipperary
Client Name	Tipperary County Council
Survey Type	R/D Asbestos Survey
Site Ref	PE21-196
Building Ref.	Scoil Ailbhe
Location	N/A
Extent/ Amount	N/A

Survey Date	17.2.2021	Sample No.	
Survey Company	Phoenix Environmental Safety Ltd.		
Testing Laboratory	G & L Consultancy Ltd.		

MATERIAL ASSESSMENT		PRIORITY ASSESSMENT	
Product type	N/A	Normal occupant activity	N/A
Extent of damage	N/A	Likelihood of disturbance	N/A
Surface treatment	N/A	Human exposure potential	N/A
Asbestos type	N/A	Maintenance activity	N/A
Material assessment score: N/A		Priority assessment score: N/A	
TOTAL SCORE: N/A			

CONCLUSIONS AND RECOMMENDATIONS


**NO ASBESTOS CONTAINING
MATERIALS DETECTED**

APPENDIX D

NON ASBESTOS CONTAINING MATERIALS



Modern roofing membrane



Plastic water tanks

NON ASBESTOS CONTAINING MATERIALS



Black toilet cisterns sampled



Double glazed windows

NON ASBESTOS CONTAINING MATERIALS




Textured coating sampled



Felt pads on sinks sampled

NON ASBESTOS CONTAINING MATERIALS



Terrazzo flooring



Vinyl floor tiles sampled

APPENDIX E

NON ACCESSIBLE LOCATIONS

- The school was live and in use during the asbestos survey and destructive surveying and sampling was curtailed in some areas
- The flat roof areas were not sampled to prevent leaks
- No fixed floor finishes (ceramic tiles or timber floorboards) were lifted or inspected
- No inspection of live electrical or mechanical plant or similar requiring the attendance of a specialist engineer was carried out
- No inspection of any areas requiring specialist access equipment other than telescopic ladder was carried out
- No underground services or confined spaces were inspected
- All contractors working on the site should always remain vigilant to the possibility that concealed asbestos containing materials may be present on site. If any suspect asbestos containing materials are uncovered during the course of the work, works must stop in that area and the suspect material should be sampled and analysed immediately for the presence of asbestos

APPENDIX F

FLOOR PLANS & LOCATION OF ASBESTOS CONTAINING MATERIALS

Schematic diagram only Not to scale 22nd February 2021	Scoil Ailbhe, Parnell Street, Thurles, Co. Tipperary