

St Josephs Hospital Stranorlar, Co. Donegal
Replacement Boundary Wall Site Photos



Stone wall to be replaced



Stone wall to be replaced, concrete slab & tarmac to be reinstated where required



Existing Driveway – No Access for Heavy Plant, Pedestrian Access only



Hedge to be removed - St Josephs side (March 2025)



Trial hole June 2025



Google Streetview 2021 – Storm manhole & wall to be demolished & rebuilt post works



Garden / landscaped area – Proposed new drainage route



Rear of wall at footpath



Storm manhole



Storm manhole – Invert levl 725mm below road



Garden / landscaped with 2 manholes for eircom & watermain & tree to be removed



Proposed new drainage route between hedge & watermain manhole



Approx 1.55m for proposed new drainage route between hedge & watermain manhole



Watermain Manhole- base approx 0.9m below ground level



Eircom Manhole - base approx 0.73m below ground level



Proposed site access location (September 2026)



Proposed site access location (September 2026)