

Condition Report of Existing Welfare Unit

Document: TRA-00-10-03-07

Produced by
Meath County Council
Buvinda House
Dublin Road
Navan
County Meath
C15 Y291
Tel: (046) 9097000
Fax: (046) 9097001
www.meath.ie
customerservice@meathcoco.ie



Contents

Introduction 2

Size of existing unit 2

Service Disconnection 2

Photographs of Existing Unit for Removal 3

Introduction

This document is to provide tenderers some information on the existing welfare unit for removal from the Dunshaughlin Depot as part of the scope of works required.

All measurements are approximate and are intended to give tenderers an idea of size and scale of the existing unit.

Meath County Council take no responsibility for the condition or integrity of the existing unit or discrepancies in outlined dimensions below. Tenderers are invited to inspect the unit at Dunshaughlin Depot to inform themselves of the existing condition, transport requirements and reuse potential. A date for site inspection is set out in the instructions to tenderers.

Size of existing unit

The approximate size of the existing unit is set out below:

- Length – 9140mm
- Width – 3050mm
- Height at Apex – 2.75m
- Window sizes - circa 1000 x1000mm
- External wall thickness – circa 100mm

Service Disconnection

The existing unit will be disconnected from water, wastewater and electrical connections by Meath County Council contractors prior to removal.

Photographs of Existing Unit for Removal



Front view



Side View 1



Rear View



Side View 2



Corridor View 1



Corridor View 2




Corridor View 3



Corridor View 4



Drying Room View 1



Drying room View 2



Drying room View 3



Drying room View 4



Drying room View 5



Toilet Room



Shower Room



Storage Room View 1



Storage Room View 2



Storage Room View 3



Storage Room View 4