


TRIAL HOLE LOG

TRIAL HOLE NO. TH01

Project:	Raheen GWS Watermain Replacement	Date Excavated:	17-7-2026
Client:	Bodyke Raheen Co-Operative Ltd	Logged By:	FC
Location / Chainage:	SEE DRAWING	Ground Level (mOD):	51.7
Excavation Method:	2 ton excavator	Coordinates (E, N):	563915,682695

TRIAL HOLE SECTION		STRATA DESCRIPTION				
Existing Ground Level  Base of Trial Hole	Stratum	Description / Field Observation	Thickness (m)	Depth to Base (m)	Remarks	
	Topsoil	Topsoil as identified on trial hole log.	0.15	0.15		
	Stone / Gravel	Loose stone / gravel.	0.40	0.55		
	Boulder Clay	Boulder clay to base of trial hole.	0.65	1.20		
Total Depth (m)			1.20			

ADDITIONAL INFORMATION		PHOTOGRAPH(S)	
Groundwater Encountered:	NO		
Stability of Trial Hole:	GOOD		
Samples Taken:	NO		
Services / Obstructions:	NO		
Other Relevant Information:			

Remarks / Conclusions:	
------------------------	--