


TRIAL HOLE LOG

TRIAL HOLE NO. TH03

Project:	Raheen GWS Watermain Replacement	Date Excavated:	17-7-2026
Client:	Bodyke Raheen Co-Operative Ltd	Logged By:	FC
Location / Chainage:	SEE DRAWING	Ground Level (mOD):	78.47
Excavation Method:	2 ton excavator	Coordinates (E, N):	564383,682615

TRIAL HOLE SECTION		STRATA DESCRIPTION				
Existing Ground Level  Base of Trial Hole		Stratum	Description / Field Observation	Thickness (m)	Depth to Base (m)	Remarks
		Topsoil	Topsoil as identified on trial hole log.	0.10	0.10	
		Stone / Gravel	Loose stone / gravel.	0.50	0.60	
		Boulder Clay	Boulder clay to base of trial hole.	0.5	1.10	
Total Depth (m)				1.10		

ADDITIONAL INFORMATION		PHOTOGRAPH(S)	
Groundwater Encountered:	NO		
Stability of Trial Hole:	GOOD		
Samples Taken:	NO		
Services / Obstructions:	NO		
Other Relevant Information:	A 225mm DIAMETER PLASTIC STORM CROSSES AT THIS LOCATION WITH CROWN LEVEL CIRCA 200mm BGL		
Remarks / Conclusions:			