


TRIAL HOLE LOG

TRIAL HOLE NO. TH05

Project:	Raheen GWS Watermain Replacement	Date Excavated:	17-7-2026
Client:	Bodyke Raheen Co-Operative Ltd	Logged By:	FC
Location / Chainage:	SEE DRAWING	Ground Level (mOD):	90.58
Excavation Method:	2 ton excavator	Coordinates (E, N):	565452,682271

TRIAL HOLE SECTION		STRATA DESCRIPTION				
Existing Ground Level  Base of Trial Hole		Stratum	Description / Field Observation	Thickness (m)	Depth to Base (m)	Remarks
		Topsoil	Topsoil as identified on trial hole log.	0.150	0.15	
		Stone / Gravel	Loose stone / gravel.	0.300	0.45	
		Boulder Clay	Boulder clay to base of trial hole.	0.650	1.10	
Total Depth (m)				1.10		

ADDITIONAL INFORMATION		PHOTOGRAPH(S)	
Groundwater Encountered:	NO	 ESB DUCT	
Stability of Trial Hole:	GOOD		
Samples Taken:	NO		
Services / Obstructions:	NO		
Other Relevant Information:	THERE IS AN ESB DUCT RUNNING ALONGSIDE EXCAVATION AT 300mm ABOVE BOTTOM OF PIT.		
Remarks / Conclusions:			